

MA07-150 CEILING SHOWER ARM


meir.






MA07-300 CEILING SHOWER ARM

meir.




- Clean using a mild washing soap solution rinsed, and dry with a soft cloth.
- Check for any product defects before installation.
- Refer to the installation manual for correct installation.




MHO4 SHOWER ROSE

meir.®




FLOW RATE GRAPH



CREDENTIALS

- Watermark AS/NZS3718WMKA25013
- Wels Rated 3 Star




| No. | Part Name |
|-----|-----------------|
| 1 | Strainer |
| 2 | Flow Controller |
| 3 | Nut |
| 4 | Wearing Ring |
| 5 | Universal Ball |
| 6 | Wearing Ring |
| 7 | Screw |
| 8 | Connet Nut |
| 9 | O-ring |
| 10 | Cover Plate |
| 11 | Connector |
| 12 | Rubber Gasket |
| 13 | Plate |




MH05 SHOWER ROSE

meir.®




FLOW RATE GRAPH



CREDENTIALS

- Watermark AS/NZS3718WMKA25013
- Wels Rated 3 Star




| No. | Part Name |
|-----|-----------------|
| 1 | Strainer |
| 2 | Flow Controller |
| 3 | Nut |
| 4 | Wearing Ring |
| 5 | Universal Ball |
| 6 | Wearing Ring |
| 7 | Screw |
| 8 | Connet Nut |
| 9 | O-ring |
| 10 | Cover Plate |
| 11 | Connector |
| 12 | Rubber Gasket |
| 13 | Plate |




MH06 SHOWER ROSE

meir.®




FLOW RATE GRAPH



CREDENTIALS

• Watermark AS/NZS3718WMKA25013

• Wels Rated 3 Star



| No. | Part Name |
|-----|-----------------|
| 1 | Strainer |
| 2 | Flow Controller |
| 3 | Nut |
| 4 | Wearing Ring |
| 5 | Universal Ball |
| 6 | Wearing Ring |
| 7 | Screw |
| 8 | Connet Nut |
| 9 | O-ring |
| 10 | Cover Plate |
| 11 | Connector |
| 12 | Rubber Gasket |
| 13 | Plate |